


FIG. 1 is a schematic diagram of a mechanical assembly. The assembly includes two large circular components, 1 and 2, which are positioned vertically. Component 1 is at the top, and component 2 is at the bottom. A horizontal line, 18, is positioned below component 2. A small circular component, 12, is located at the point of contact between component 2 and line 18. A rectangular component, 3, is positioned to the right of component 1. A rectangular component, 4, is positioned to the left of component 2. A rectangular component, 5, is positioned to the left of component 1. A rectangular component, 6, is positioned to the right of component 2. A rectangular component, 7, is positioned to the right of component 1. A rectangular component, 8, is positioned to the right of component 1. A rectangular component, 9, is positioned to the left of component 1. A rectangular component, 10, is positioned to the left of component 1. A rectangular component, 11, is positioned to the left of component 1. A rectangular component, 13, is positioned to the right of component 2. A rectangular component, 14, is positioned to the right of component 2. A rectangular component, 15, is positioned to the left of component 2. A rectangular component, 16, is positioned to the left of component 2. A rectangular component, 17, is positioned to the left of component 2. A rectangular component, 19, is positioned to the right of component 2.



**FIG 1**

**Signature of Contributor**

**Date**

- 1.
- 2.
- 3.
- 4.




FIG. 2




Fig 3